



Digital Gauss Meter

CONTACT US

Phone: 310-830-6601

FAX: 310-830-9336

Email: info@sepor.com
& services@sepor.com

LOCATIONS

WEST COAST

718 N. Fries Avenue
Wilmington, CA 90744

EAST COAST

3740 NW 124th Ave
Coral Springs, FL 33065



Description:

This meter immediately displays the DC or AC magnetic field and warms up in ½ second. It does not require initial calibration or adjustments. It can be rapidly scanned across a part to check for magnetization. The meter's alarm will sound when it encounters a magnetic field that exceeds the set point. The meter operates on a 9-volt battery or AC adapter (110-240 VAC).

Catalog# 060L-001 – Gauss meter with transverse probe